


ST Sylvester Church, Chivelstone ~ Pulpit Conservation



Clockwise from top left: Before conservation; Solvents applied to the area through Japanese tissue; Tissue carefully removed after a specified dwell time and the softened varnish is removed using cotton wool swabs; The conserved area is neutralised.